Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: BEULAH 2 CTB

Field Name: MEDICINE POLE HILLS Well File #:

Date Incident:2/14/2015Time Incident:11:00Facility ID Number:405456-06County:BOWMANTwp:129Rng:104Sec:4Qtr:NW NW

Location Description:

Submitted By: Shane Knuchel Received By:

Contact Person: Shane Knuchel

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 66 Barrels 66 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/1/2015 Clean Up Concluded: 2/25/2015

Risk Evaluation:

None

Areal Extent:

Impacted area runs 300 yards down drainage in a narrow path.

Potential Environmental Impacts:

Topsoil

Action Taken or Planned:

Impacted area has been diked and contained. Impacted area will be flushed and or soil removed depending on extent of contamination.

Wastes Disposal Location: TBD

Agencies Involved: Notified Tom Delling NDIC by phone on 2/14/2015 at 7:31 PM CT.

Updates

Date: 2/16/2015 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank overflow ran off location and down a drainage. Followup is necessary.

Date: 2/26/2015 Status: Inspection Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 0920. At the time of the site visit, the impacted area had been scraped up, and the impacted soils and vegetation had been disposed of. Continental Resources' third-party consultant collected both soil confirmation samples and water samples of released brine. Awaiting confirmation sampling results. If sampling results indicate that remediation was successful, then reseeding will occur in spring.

Date: 6/3/2016 Status: Inspection Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on 4/25/16 at 2:01 p.m. Vegetation in the impact area is returning and appears healthy. Continental Resources collected confirmation samples from the site. Concentrations for chlorides and sodium adsorption ratio (SAR) are below cleanup standards in the samples. No further action is warranted.

Date: 6/6/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.